

Removal of Coatings and Old Paint Layers from Building



Our partner in Singapore, the company HWT, won a contract to remove old layers of paint and coatings from a building facade.

The aim was to lay open the natural stonework.

Photo on the right :

The work was carried out with KAMAT machines

Performance:

Working pressure: **2.500 bar**
Capacity **23 l/min**



Photo on the left:

Service technician working from the scaffolding.

He is using a KAMAT "**Roto-Lance**".

Removal of Coatings and Old Paint Layers from Building



Photo on left:

The "**Roto-Lance**" in operation. Formerly, jobs of this nature could only be successfully carried out by the sandblasting method.

But this method is now prohibited in residential areas, due to the high rate of dust formation.

Photo on the right:

Wherever scaffolding was not practicable, hydraulic platforms were used.



Photo on the left:

All coatings and paint layers were successfully removed from the stone ornaments, without causing any damage.

At the top of the picture the original coatings are still visible.